

الزامات فنی

Row	Aks	Ident	Type	Pn (bar)	Range	Adjust	Process connection	Electrical connection	Minimum Damping	Power supply *	Fuji برند
1	NG 51/59 F001/2	FAIR BRN 11	Δp	2.5	0 - 10 mbar	0 - 61.2 mm	1/4 " - 18 NPT	M20*1.5	۳۲ ثانیه	24 Vdc	FKC311V6-2XKBY- CL
13	SD 01 P 003	PAIR INL CNDR	p	40	0 - 1.6 ata	0 - 1.5 ata	1/4 " - 18 NPT	M20*1.5	۳۲ ثانیه	24 Vdc	FKA303V6-2XKBY- CL
41	SA 11 P 031	P WEEL CHm BR	p	160	0 - 100 bar	0 - 100 at	G 1/2"A manometer fittin	M20*1.5	۳۲ ثانیه	24 Vdc	FKP804V6-2XKBY- EL